

CAMBRIDGE ASBESTOS REMOVAL

The Specialist in Asbestos

Ceilings ~ Roofs ~ Garages ~ Waste Collection ~ Pipes ~ Boilers ~ Surveys
Artex ~ Analysis ~ Water Tanks ~ Floors ~ Soffits ~ Licence 4040504940

Tel: 01223 240100 / 01284 852414

CONFIRMATION OF REMOVAL

This document is confirmation of decontamination
Of 3 world war two gas masks.

The gas masks were dismantled in a controlled environment and samples of
various materials were taken and analysed. From these results, all asbestos
containing materials were removed and the masks were re-assembled.

The masks cleaned were: WW2 civilian gas mask
WW2 child's gas mask
WW2 baby gas mask

November 2009

Signed.....*clackridge*.....

Date.....*30/11/09*.....

Cambridge Asbestos Removal Ltd

Tel: **Cambridge** 01223 240100
Ipswich 01473 464000
Bury st Eds 01284 852414
Peterborough 01733 286555

Email: cambridgeasbestosremoval@hotmail.co.uk



Unit 26, Grange Mill, Chevington, Bury St Edmunds, Suffolk, IP29 5PQ

Fax: 01284 852414 Email: cambridgeasbestosremoval@hotmail.co.uk

www.happeninghistory.co.uk

ASBESTOS FIBRE IDENTIFICATION REPORT

PRIVATE AND CONFIDENTIAL



Client Address:

FAO: Barry Bridges
CAMBRIDGE ASBESTOS REMOVAL
26 Grange Mill
Chevington
Bury St Edmunds
SUFFOLK
IP29 5PQ



HEAD OFFICE
ENVIRONTEC HOUSE
THE STREET
HATFIELD PEVEREL
CHELMSFORD
ESSEX
CM3 2EJ
TEL 01245 381900
FAX 01245 381666
E-Mail:
enquiries@envirotec.com
Website: www.envirotec.com

ALSO OFFICES IN
LEEDS
LONDON
EIRE
GIBRALTAR

REPORT NO:	BO61308	Site Address:	Gas Mask From World War II
JOB NO:	30183/MS/BA	Final Issue date:	12 November 2009

Name of analyst:	Anna Gebal	Sampled by:	Client
Date sample taken/receipt	11/11/09	Date of analysis	11/11/09

RESULTS:

SAMPLE REF:	LOCATION/ DESCRIPTION:	MATERIAL TYPE: (see Technical Note)	ASBESTOS FIBRE TYPE:
BS321302	GREEN FILTER MATERIAL	LINT	NO ASBESTOS DETECTED
BS321303	BLACK FILTER MATERIAL	LINT	CHRYSTOTILE
BS321304	CARBON MATERIAL	CARBON	NO ASBESTOS DETECTED

METHOD STATEMENT:

ANALYSIS WAS PERFORMED IN ACCORDANCE WITH OUR UKAS ACCREDITATION BASED ON IN-HOUSE DOCUMENTED TECHNICAL METHODS AND THE HSG 248 "ASBESTOS: THE ANALYSTS GUIDE" TO DETERMINE THE PRESENCE OF ASBESTOS FIBRES. CALIBRATION OF EQUIPMENT AND GENERAL QUALITY CONTROL PROCEDURES ARE IN ACCORDANCE WITH OUR IN-HOUSE QUALITY CONTROL DOCUMENT. SAMPLING METHODS ARE IN ACCORDANCE WITH DOCUMENTED IN-HOUSE PROCEDURES AND UKAS ACCREDITATION.

ASBESTOS FIBRE IDENTIFICATION REPORT

PRIVATE AND CONFIDENTIAL



Client Address:

FAO: Barry Bridges
CAMBRIDGE ASBESTOS REMOVAL
26 Grange Mill
Chevington
Bury St Edmunds
SUFFOLK
IP29 5PQ



HEAD OFFICE
ENVIRONTEC HOUSE
THE STREET
HATFIELD PEVEREL
CHELMSFORD
ESSEX
CM3 2EJ
TEL 01245 381900
FAX 01245 381666
E-Mail:
enquiries@envirotec.com
Website: www.envirotec.com

ALSO OFFICES IN
LEEDS
LONDON
EIRE
GIBRALTAR

REPORT NO:	BO61308	Site Address:	Gas Mask From World War II
JOB NO:	30183/MS/BA	Final Issue date:	12 November 2009

Name of analyst:	Anna Gebal	Sampled by:	Client
Date sample taken/receipt	11/11/09	Date of analysis	11/11/09

RESULTS:

SAMPLE REF:	LOCATION/ DESCRIPTION:	MATERIAL TYPE: (see Technical Note)	ASBESTOS FIBRE TYPE:
BS321302	GREEN FILTER MATERIAL	LINT	NO ASBESTOS DETECTED
BS321303	BLACK FILTER MATERIAL	LINT	CHRYSTOLE
BS321304	CARBON MATERIAL	CARBON	NO ASBESTOS DETECTED

METHOD STATEMENT:

ANALYSIS WAS PERFORMED IN ACCORDANCE WITH OUR UKAS ACCREDITATION BASED ON IN-HOUSE DOCUMENTED TECHNICAL METHODS AND THE HSG 248 "ASBESTOS: THE ANALYST'S GUIDE" TO DETERMINE THE PRESENCE OF ASBESTOS FIBRES. CALIBRATION OF EQUIPMENT AND GENERAL QUALITY CONTROL PROCEDURES ARE IN ACCORDANCE WITH OUR IN-HOUSE QUALITY CONTROL DOCUMENT. SAMPLING METHODS ARE IN ACCORDANCE WITH DOCUMENTED IN-HOUSE PROCEDURES AND UKAS ACCREDITATION.